

COSCOR CONTRACTO SERVICE

STATEMENT SECONDS



AD



MTL TR 86-44

THE EFFECT OF AUSTENITIZING CONDITIONS ON THE ANISOTROPIC EMBRITTLEMENT OF ESR 4340 STEEL

October 1986

E. G. HAMBURG and A. D. WILSON Lukens Steel Company Research Center Coatesville, PA 19320

**FINAL REPORT** 

Contract DAAG46-85-C-0011

Approved for public release; distribution unlimited.



Prepared for

U.S. ARMY MATERIALS TECHNOLOGY LABORATORY Watertown, Massachusetts 02172-0001

86 12 22 005


THE FILE COPY

REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM							
MTL TR 86-44  AD-A175	3 RECIPIENT'S CATALOG NUMBER							
4. TITLE (and Subtitle)	5 TYPE OF REPORT & PERIOD COVERED							
THE EFFECT OF AUSTENITIZING CONDITIONS ON THE ANISOTROPIC EMBRITTLEMENT OF ESR 4340 STEEL	Final Report 1/15/85 to 10/31/86							
ANIBOTROI TO MIDRITIDE OF THE CO. C.	6 PERFORMING ORG REPORT NUMBER							
7. AUTHOR(a)	B. CONTRACT OR GRANT NUMBER(s)							
E. G. Hamburg and A. D. Wilson	DAAG46-85-C-0011							
9. PERFORMING ORGANIZATION NAME AND ADDRESS	10 PROGRAM ELEMENT PROJECT, TASK AREA & WORK UNIT NUMBERS							
Lukens Steel Company Research Center	D/A Project: 1A4632150079							
Coatesville, PA 19320	AMCMS Code: 694000.166							
U.S. Army Materials Technology Laboratory	12. REPORT DATE							
ATTN: SLCMT-ISC	October 1986							
Watertown, MA 02172-0001	54							
14 MONITORING AGENCY NAME & ADDRESS(if different from Controlling Office)	15. SECURITY CLASS (of this report)							
	Unclassified							
	15a. DECLASSIFICATION DOWNGRADING SCHEDULE							
16. DISTRIBUTION STATEMENT (of this Report)								
Approved for public release; distribution unlimi	Approved for public release; distribution unlimited.							
17 DISTRIBUTION STATEMENT (of the abstract entered in Bluck 20, if different fro	om Report)							
18 SUPPLEMENTARY NOTES								
19 KEY WORDS (Continue on reverse side if necessary and identify by block number								
4340 Steel Mechanical propert	2103							
Electroslag remelting Fracture toughness Heat treatment Anisotropy	5							
Heat treatment Anisotropy								
20 ABSTRACT (Continue on reverse side if necessary and identify by block number)								
(SEE REVERSE SIDE)								

# Block No. 20

### **ABSTRACT**

-The effect of austenitizing conditions on the anisotropic embrittlement of electroslag remelted (ESR) 4340 steel were studied. Increasing austenitizing temperature from 1550°F to 1750°F had little or no effect on the strength and toughness of ESR melted 4340 steel. Decreasing the quench rate from 1000°F per minute to 500°F per minute had no effect on the strength and toughness. Decreasing the quench rate from 500°F per minute to 100°F per minute had a significant effect on Charpy V-notch toughness. Lower Charpy V-notch toughness associated with the quench rate of 100°F per minute was due to the presence of bainite in the microstructure. The presence of bainite had a small effect on slow bend fracture toughness. Plate anisotropy was yery small in the plane of the plate (longitudinal versus transverse). Properties normal to the plane of the plate were affected drastically. Charpy V-notch toughness was decreased as much as 56% over the values obtained in the longitudinal direction. Reduction in area of the mild notch tensile specimen was decreased as much as 64% in the through-thickness direction when compared to the longitudinal direction. Inclusion clusters were primarily alumina with some calcium present. In all the tests conducted, there was no evidence for anisotropic embrittlement of this material (i.e., intergranular fracture).



# INTRODUCTION

THE SERVICES PROJECTED WINDLESS STANDARD WINDS

Electroslag Remelted (ESR) processed, high hardness (55HRC) 4340 steel has been reported to exhibit superior ballistic properties for armor applications (1,2). These benefits are primarily due to the low sulfide inclusion content resulting from ESR processing. However, other studies have raised a concern of anisotropic embrittlement\* of this steel during heat treatment, particularly in the short transverse orientation (3). To investigate the potential influences of heat treatment on this embrittlement, a thorough study was undertaken. The study in estigated austenitizing temperatures of 1550, 1650 and 1750° F (843, 899, 954° C) and quenching rates of 100, 500 and 1000° F/min. (56, 278, 555° C/min.). These levels were felt to reflect the full range of practices that may be used in heat treating this steel. The influences of these heat treatments on the tensile, Charpy V-notch (CVN), impact toughness and K<sub>IC</sub>, fracture toughness were evaluated in the three major testing orientations for a one-half inch thick ESR 4340 plate. Comprehensive metallographic evaluations also accompanied this testing, including extensive scanning electron microscopic (SEM) fractography.

The benefits of ESR processing are often confirmed by a reduction in sulfur content to very low levels (less than 0.005 w/o). However, the reduction in overall inclusion content and morphology of the remaining inclusions also has a beneficial effect on behavior (4,5). ESR processing involves remelting of a 4340 steel electrode through a molten slag, which chemically and physically removes

<sup>\*</sup> Varying degrees of embrittlement depending on testing orientation.

the manganese sulfide and aluminum oxide inclusions that are present in conventionally produced steels. The molten steel is subsequently solidified in a copper water-cooled mold. The cooling rates in the mold tend to promote smaller, well dispersed inclusions, when compared to conventional ingot steel production. The remaining inclusions are also found to be calcium modified, when the refining slag contains CaO<sup>(5)</sup>. In particular, calcium aluminates are a primary inclusion found in ESR steels. Therefore in this study, to further identify the potential variables influencing the toughness of ESR 4340 steels, the non-metallic inclusions found on the tensile, CVN and K<sub>IC</sub> fracture surfaces were characterized.

To obtain specimens in the short transverse testing orientation, a novel cutting and welding of extension material was used prior to austenitizing and quenching of test plates. Although the hazards of quench cracking resulted in difficulty in obtaining specimens in all testing conditions, enough were successful to continue use of this procedure. These procedures will be discussed in more detail in the following sections.

# MATERIALS AND PROCEDURE

ecce magnitude societies bibliophy. Investigat isophysix

An ingot of 4340 steel was electroslag remelted (ESR) to the chemistry shown in Table 1. A portion of this ingot was rolled to 1/2 inch plate for evaluation. The variables of concern are the effect of austenitizing temperature, cooling rate during quenching and the plate anisotropy resulting from the rolling process. Three austenitizing temperatures of  $1550^{\circ}$ ,  $1650^{\circ}$  and  $1750^{\circ}$  for

1 hour were used on the material. Specimens were coded 15, 16 and 17, respectively. Nominal quench rates of  $100^{\circ}$  F per minute (A),  $500^{\circ}$  F per minute (P) and  $1000^{\circ}$  F per minute (W) were carried out on the material.  $1000^{\circ}$  F per minute was achieved by quenching into water,  $500^{\circ}$  F per minute was achieved by cooling in a controlled air jet and  $100^{\circ}$  F per minute was achieved by cooling in air.

Specimens were tempered between  $340^\circ$  F and  $390^\circ$  F for 1 hour to achieve uniform hardness of approximately 55 HR in all samples. Table 2 summarizes the heat treating and shows the resulting hardness.

Standard\* Charpy V-notch samples and standard\* 0.252 tensile samples were prepared and machined in the L-T\*\* direction (L) and T-L\*\* direction (T). Slow bend fracture toughness specimens\*\* were prepared in the L direction only. Specimen blanks were prepared for testing in the short transverse direction by welding 1/2 inch thick extensions normal to the surface of the plate and then machining off the original plate excess. These blanks were then heat treated as described above. After heat treating, the blanks were then used to prepare standard CVN specimens with the notch oriented in the S-L (S) direction.

Fracture surfaces were examined using scanning electron microscope (SEM) and analysis of inclusion was carried out using energy dispersive X-ray analysis (EDXA).

STATE OF THE PROPERTY OF THE P

<sup>\*</sup> ASTM A370

<sup>\*\*</sup> Per ASTM E399

# RESULTS

# Heat Treating and Microstructure

Table 2 exhibits the austenitizing temperature, quench rate, tempering temperature and Rockwell C hardness of the materials examined. The microstructures of the 3 cooling rates are shown in Figures 1, 2 and 3 in the quenched and tempered condition. For the W and P conditions the microstructures are 100% martensite. The A condition resulted in small amounts of bainite in the sample. It appears that the sample austenitized at 1650°F had approximately 10% bainite while the samples austenitized at 1750°F and 1550°F had less than 7% bainite. The bainite in Sample 16A was banded to a greater degree than in 15A and 17A.

The presence of a small amount of bainite when the cooling rate is  $100^{\circ}$  F per minute is expected. Calculations<sup>(6)</sup> of the critical cooling rate (CCR) for 100% martensite indicate that bainite can be expected for cooling rates less than  $200^{\circ}$  F per minute.

# Mechanical Properties

Table 3 presents the results of tensile tests, Charpy V-notch toughness at ambient temperature (RT) and -40° F, and slow bend fracture toughness at RT. The tensile test results for standard specimens oriented in the short transverse direction (S) were invalid because the samples necked down in the weld region giving low strength and ductility. No test samples were obtained for 15 PS, 16 PS, 16 WS, 17 PS and 17 WS conditions because quench cracks developed in the sample blanks during heat treatment. Figure 4 compares yield strength and tensile strength of L and T samples only. The yield strength of the slow cooled samples (A) were significantly lower than the W or P samples. The effect of cooling rate on tensile strength was comparatively less. The water quenched samples (W) had the highest yield strengths.

Weld failures were experienced while tensile testing specimens oriented in the through thickness (S) direction. Therefore, mild notch samples were prepared from the remaining standard samples in order to compare the strengths and ductility in the three test directions. The notches were oriented in the welded section of the S sample so that the minimum diameter was located at the centerline of the plate. The specimens consist of a 3/8" diameter notch with a root diameter of 0.150". The 0.2 percent offset was estimated from the load elongation curve. Table 3 contains the test results. Figure 5 shows the reduction in area plotted as a function of tensile strength. The specimens oriented in the short transverse (S) direction exhibit significantly lower ductility than in the L and T direction. The reduction in area for the short transverse (S) direction was between 9.8% and 11.9%. As shown in Figure 6, the air cooled (A) sample exhibited consistently lower reduction in area in the L and T direction than the P or W samples (22.2% to 28.3% for the A samples versus 33.2% to 37.3% for the P or W samples).

COOK SERVING SERVINGS DECEMBER OF SERVINGS OF SERVINGS

"GRASSESSE" DOGGOGGE DOGGOGGE

The presence of bainite lowers the yield strength and the tensile ductility of air cooled samples. The lower strength of the bainite component together with the coarse carbides associated with its formation act as sites for premature void formation or fracture nucleation. Thus the lower ductility of the A samples.

Figure 7 presents the relationship between Charpy V-notch toughness at  $70^{\circ}$  F and yield strength. The Charpy V-notch toughness at  $70^{\circ}$  F showed behavior similar to the reduction in area behavior. Short transverse orientation at  $70^{\circ}$  F exhibited values between 6 and 10 foot pounds. There appeared to be no effect of either cooling rate or austenitizing temperature for samples tested in the

short transverse direction. For the L and T samples, the A cooling rate had significantly lower toughness than cooling rates P or W, despite having a lower yield strength. For the P and W Charpy results at  $-40^{\circ}$  F, the L and T orientation austenitized at  $1550^{\circ}$  F appeared to give slightly higher toughness than samples austenitized at  $1650^{\circ}$  F and  $1750^{\circ}$  F (Fig. 8).

Fracture toughness measured in the L direction showed very little variation with either cooling rate or austenitizing temperature. The A samples showed slightly lower values than the P or W samples and there appeared to be a slight increase in fracture toughness for the  $1750^{\circ}$  F austenitizing temperature. Figure 9 compares  $K_Q$  with Charpy V-notch toughness measured at  $70^{\circ}$  F in the L orientation.  $K_Q$  exhibits very little variation as compared to the Charpy V-notch variation.

# **METALLOGRAPHY**

(SSS) Sections (SSSSSSS) Sections (Section Management

# Fractography - CVN

Figures 10 thru 12 show the fracture surface of CVN samples 15 AS, 15 AT, 15 PT, 15 WT and 15 WS. The transverse (T) samples of the intermediate (P) quenched samples and rapidly (W) quenched samples are characterized by dimpled rupture (see Figs 11A and 11B). The "dimples" that developed have a large range in size. Generally, they are free of any detectable second phase particles. A few small inclusions, located on these surfaces, contained Al and Ca. The sample that was slow quenched (A) showed an increased amount of quasi-cleavage when compared to the P and W sample (see Fig. 10B). The fracture surface of the sample oriented in the S direction (Fig. 12) was characterized by dimpled rupture. However, in this case there was evidence that small inclusions were

involved in the development of the void. The inclusions contained primarily Al and in some cases a minor amount of Ca. Fig. 10A shows the fracture surface of the 15 AS sample and Fig. 12A and 12B gives the fracture surface of sample 15 WS.

The CVN fracture surfaces for the steels austenitized at 1650° and 1750° F are shown in Figs. 13 thru 16. In all cases, the fracture surfaces are characterized by dimpled rupture. Quasi-cleavage is present but is not a prominent feature. Inclusions were difficult to find.

# Fractography - K Sample

Figs. 17 thru 21 present the fracture surfaces of the slow bend fracture toughness ( $K_Q$ ) samples at 1000%. The samples are a mixture of dimpled rupture and quasi-cleavage. The similarity between the fracture surface morphologies reflects the similarity between the fracture toughness values measured, despite the differences in microstructure of the A samples versus the P and T samples. The presence of bainite in the microstructure does not alter the fracture surface appearance significantly.

### Inclusion Characterization

A sample of steel in the heat treated condition was sectioned and polished parallel to the L, T and S planes of the original plate. Very few inclusions were observed when viewing parallel to the L and T direction. Small clusters of inclusions were visible on the section parallel to the S direction. Fig. 22A shows a cluster from the S plane and Fig. 22B shows two inclusions from the center of this cluster at a magnification of 2600X. The duplex inclusion marked at A exhibited an EDXA spectrum (Fig. 23) containing Nb, Al, V and Ti. The light area is apparently an Nb carbo-nitride (CN) with V and Ti in solution and the dark area an alumina particle. The area marked B is primarily an alumina

particle containing a trace of calcium as shown by the spectrum shown in Fig. 24.

Fig. 25 shows a duplex Nb-Ti-CN. The area marked C is rich in Ti and Nb with a small amount of V (Fig. 26). Area D is apparently a Nb-CN with a minor amount of Ti and a trace of V in solution (Fig. 27). It is postulated that these particles form when the steel is in the molten state. The presence of alumina particles adjacent to the Nb-Ti-CN suggests that the alumina can act as a nuclei for precipitation of the Nb-Ti-CN during solidification. The area E in Fig. 25B is an alumina inclusion as shown by the EDXA spectrum in Fig. 28.

Fig. 29A shows the fine inclusion in the cluster in Fig. 25B at 2600X. The particle F in Fig. 29A contains primarily Al with Ca, Ce and Mg as trace elements (see Fig. 30). Fig. 29B presents a section parallel to the longitudinal section. Clusters of inclusions were not visible on this section. The inclusions were isolated and typical of the inclusions shown in Fig. 29B. The inclusion marked G, analysed by EDX-A, contained primarily Al and Ca as a minor constituent (see Fig. 31). The small tails shown adjacent to the inclusion marked H and shown at higher magnification in Fig. 32 contained Mn and S (Fig. 33). The Al, Cr and Fe peaks are matrix emissions from the steel or the adjacent alumina inclusion.

Fig. 34A contains views parallel to the transverse section. The inclusions marked J and K were alumina. The inclusion J contained small amount of Ca (see Fig. 35) while the inclusion marked K contained only Al (see Fig. 36). The inclusion marked L in Fig. 34B is apparently a Ti-CN with Nb in solution (Fig. 37).

Additional inclusion analysis generally followed the trends discussed above. The bulk of the inclusions were alumina, some contained small amount of

Ca. Rare earths (Ce) were sometimes detected as a trace element. Sulphides, when detected, were associated with larger alumina inclusions. In no case were any sulphide stringers located. Fracture surfaces of CVN specimens and notch tensile specimens were generally free of inclusions. When inclusions were found on these surfaces, they generally analyzed as alumina often containing Ca as a minor constituent. Sulphides were never located on the fracture surfaces. The only sample that had inclusions on the surface to any degree was the 15 AS notch tensile sample. These inclusions analyzed as alumina inclusions and no sulphides were detected.

The lack of inclusions on the fracture surfaces of the L and T CVN samples and the overall bulk cleanliness suggests that the toughness of the steel in the L and T direction is limited by microstructural features. Significant differances were found between the toughness (and ductility) of the slow cooled samples (A) and the intermediate cooled (P)-rapidly cooled samples (W). The slow cooled samples contained a small amount of bainite, while the more rapidly cooled samples were 100% tempered martensite.

# Fractography - Notch Tensile Samples

post recessor probably appointed beneficial received

335555

The notch tensile samples fractured after necking down substantially. Final failure was characterized by classic cup-cone fracture. The reduction in area of the notch tensile sample was very sensitive to structural features that affect ductility at high hardness. Figure 38A shows the shear lip development in 15WS. The shear lip area was 49% of the final area in 15WS (Figure 35) as compared to a shear lip area that was 67% of the final area in 15WT (Figure 39). The flat area was characterized by a mixture of ductile dimpled rupture in 15WT and a mixture of quasi-cleavage and dimpled rupture in 15WS.

Initiation of fracture appears to have occurred at the center of the cupcone and then progagated radially outward until the final failure was by shear. The initiation site appears to be the region of maximum hydrostatic tension in the center of specimen as predicted by the Bridgeman analysis. Note that there are small inclusions (alumina) in this area as shown in Figure 38B. The fracture in 15WT is primarily dimpled rupture (Figure 39B).

Figure 40 presents the fracture surface of 15AS. This sample contained planar arrays (bands) of bainite. The fracture surface was made up of a combination of ductile rupture and quasi-cleavage. Figure 41 displays the surface of 15AT. The fracture surface of 15AT is similar to 15AS except that the dimpled rupture regions are more deeply developed, indicating greater toughness or ductility.

Nucleation of the fracture in the notch tensile specimens occurred in the region that developed maximum hydrostatic tension (center of specimen). Fracture progresses radially outward from this region until final fracture occurs along planar developing maximum shear stress. Initiation occurs at the weakest component present. In the case of 15WS, this appears to be at small alumina inclusions. Initiation in 15WT appears to have occurred at some fine microstructural feature. The features were too fine to identify by SEM microscopy. In the case of 15AS and 15AT, initiation appears to be within a bainite grain. The high hydrostatic developed during necking caused bainite grains to fracture thereby initiating the fracture.

Examination of notch tensile sample fracture surfaces in the other heat treated condition confirmed the above results and conclusions. There was no evidence of anisotropic embrittlement.

# DISCUSSION

The quench rates of 1000° F per minute and 500° F per minute resulted in material with similar microstructure and properties. Austenitizing temperature appears to have resulted in a slightly coarser grain size for 1750° F. The difference between longitudinal and transverse properties for these quenching conditions was very small. The slow quench rate resulted in the presence of a small amount of bainite in the microstructure. The presence of bainite had a significant effect on reducing the tensile ductility, Charpy V-notch toughness and to a lesser degree the fracture toughness.

The lack of sensitivity of the  $K_{IC}$  measurement to microstructural features, as compared to the sensitivity of the CVN specimen and the tensile specimen is related to specimen design.  $K_{IC}$  testing measures the initiation of fracture from an existing sharp crack, while a CVN specimen has a blunt notch and tensile reduction of area is measured on a smooth bar specimen. Propagation of a sharp crack under plain strain conditions in the  $K_{IC}$  test is essentially controlled by stress. In a Charpy test or a tensile test, the conditions for fracture are dependent not only on the stress level but on the plastic strain that any element of material experiences. The presence of such items as sulphides, carbides and/or the presence of a weaker constituent such as bainite primarily lowers the critical strain at which ductile rupture proceeds. The sampling volume for fracture is also greater for the CVN and tensile tests because of the larger plastic zone involved.

Specimens oriented in the short transverse or thru-thickness direction showed reduced tensile ductility and Charpy V-notch toughness for all conditions tested. The anisotropy in this direction when compared with the longitudinal

and transverse direction is quite high. Generally the tensile ductility was reduced 66% while the Charpy V-notch toughness was reduced approximately 56%. The reduction of properties in the short transverse direction is primarily attributed to the textural characteristics created by the rolling process. Microstructural features are aligned in the direction of crack propagation. These features include inclusions (sulphides and oxides), and matrix microstructural features associated with chemical banding such as bainite bands.

Fracture surfaces of the steel were generally free of sulfide and oxide inclusions. This is consistent with metallographic examination of the steel. Although no quantitative analysis was carried out on the bulk inclusion content of the steel, standard metallographic examination together with SEM - EDXA analysis indicated that this steel was extremely "clean". Inclusions tended to be in small clusters and consisted primarily of alumina. In some cases, the alumina contained calcium as a minor constituent. Sulphides, when found, were associated with the alumina inclusions. Sulphides were never found on the fracture surfaces. Traces of Ti-CN and Nb-CN were found. Small rare earth inclusions were also found in the steel. Their presence is related to a proprietary complex deoxidizer used during the ESR melting process.

The mild notch tensile specimens provided the most sensitive evaluation of the effect of microstructure on properties. Charpy V-notch toughness exhibited much more sensitivity to microstructural effects than fracture toughness,  $K_{\text{T}}$ .

# SUMMARY AND CONCLUSIONS

1. Increasing austenitizing temperature from  $1550^{\circ}$  F to  $1750^{\circ}$  F had little or no effect on the strength and toughness of Heat R3192 ESR melted 4340 steel

- 2. Decreasing the quench rate from  $1000^{\circ}$  F per minute to  $500^{\circ}$  F per minute had no effect on the strength and toughness.
- 3. Decreasing the quench rate from  $500^{\circ}$  F per minute to  $100^{\circ}$  F per minute had a significant effect on Charpy V-notch toughness. Lower Charpy V-notch toughness associated with the quench rate of  $100^{\circ}$  F per minute was due to the presence of bainite in the microstructure. The presence of bainite had a small effect on slow bend fracture toughness  $(K_{TC})$ .
- 4. Plate anisotropy was very small in the plane of the plate (longitudinal versus transverse). Properties normal to the plane of the plate were affected drastically. Charpy V-notch toughness was decreased as much as 56% over the values obtained in the longitudinal (L-T) direction. Reduction in area of the mild notch tensile specimen was decreased as much as 64% in the thru-thickness direction when compared to the longitudinal (L) direction.

CANADA CANADANA CANADAN RECESSAR ADVANCE SESSONES WINDOWN BECCONSON BECCONSON DECENDANCE

- 5. The cleanliness of the steel was very good. Inclusion clusters were primarily alumina with some calcium present. Small amounts of cerium oxides, titanium and niobium carbo-nitrides were present. Sulphides were extremely small and were associated with alumina or calcium aluminate inclusions. No elongated sulphide inclusions were found.
- 6. Fracture of both the standard tensile samples and the mild notch sample was by the development of a sharp neck and cup-cone failure. Initiation of fracture was at the center of the specimen.
- 7. In all the tests conducted, there was no evidence of anisotropic embrittlement of this material (i.e., intergranular fracture).

# Acknowledgements

The authors are grateful to Mr. Leon Kerr and Mr. James Lohr for their assistance in sample preparation, testing, metallographic preparation and examination and to Wanda Kolodjay for preparation of this report. We are also appreciative of the support, assistance and guidance of Dr. Albert Anctil of the U.S. Army Materials Technology Laboratory.

the supplies and the supplies appropriate the supplies to the

RECEIPT RESIDENT BESSELDS (BESSELD) FRANCES

# References

- (1) Hickey, Jr., A. A. Anctil and R. Chait, "The Ballistic Performance of the High Strength 4340 Steel Processed by Electroslag Remelting", Proceedings of Fracture Toughness of Wrought and Cast Steels, E. Fortner ed., ASME MPC-13, 1980, pp 219-229.
- (2) C. F. Hickey, Jr., T. S. Thomas and A. A. Anctil, "Comparison of Ballistic Performance of a Split Heat of ESR and VAR 4340 Steel", AMMRC TR 85-20, July 1985.
- (3) G. B. Olson, A. A. Anctil, T. S. DeSisto and E. B. Kulla, "Anisotropic Embrittlement in High Hardness ESR 4340 Steel Forgings", Met. Trans. A, Vol. 19A, Aug. 1983, pp 1661-1669.
- (4) R. A. Swift, "Advantages of Electroslag Remelted Steels", OTC 2799 Proceedings of Offshore Technology Conference, May 1977, pp 553-563.
- (5) A. D. Wilson, "The Effect of Advanced Steelmaking Techniques on the Inclusions and Mechanical Properties of Plate Steels", in <u>Toughness</u> Characterization and Specifications for HSLA and Structural Steels, P. L. Manganon ed., AIME, N.Y.C., 1979, pp 287-307.
- (6) R. Blundeau, et al, "Mathematical Models for the Calculation of Mechanical Properties of Low-Alloy Steel Metallurgical Products", Heat Treatment '76, 1976 Metals Society.

Table 1

TOTAL TESSESSES CONTROL BOSCOCCE CONTROL CONTR

Composition of ESR

ဒ္ဓါ	0.012
ු	0.007
<u>A1</u>	0.020
Ţį	0.003
>1	0.059
W W	0.24
5	0.76
Ni	1.65
Si	0.12
1 م	0.011
ωl	0.002
띪	0.67
ा	0.43

Table 2

Heat Treating Conditions

Hardness (HR)	55 54 56	54 55 55	55 55 55
Tempering	340	340	340
Temperature	360	360	360
(PF)	390	390	390
Quench	100	100	100
Rate	500	500	500
(*F/Min.)	1000	1000	1000
Austenitizing	1550	1650	1750
Temperature	1550	1650	1750
(PF)	1550	1650	1750
	15 A	16 A	17 A
	15 P	16 P	17 P
	15 W	16 W	17 W

Bant. 5

FECHANICAL PROFESSIONS

MESSULTS OF TENSILE TESTS, CHARKY 9-NOTEST TESTS, FEATURE TUBORREDS ESPO TESTS.

FREEDMA	(Obst. 255	ΚG	(1 si in 1/_		37. V 4#			平水水 约"1寸			40.0 x			36. 1 more			40.8 × %			514 D 104			44.0 85.			水水水 小小門子		東京 中では		
V - PUICH ERENGY	, 16s.)	PERMITTEE .	404	***	0.5T	r) • • • • • • • • • • • • • • • • • • •	p. 9	16.3	16.3		14.7	n. <del>1</del> 1	Ω. γ.	8.4	10.3	D.7	15, 6	13.7		12.7	n n		11.0	19.7	6. d	12.7	× • • • • • • • • • • • • • • • • • • •	13.0		
CHARACY U.	(+)	TEM	7.0F	**	15.0	۳. د د	0.0	18.7	18.3		18.0	18.7	o. 0	12.0	13.7	7.7	19.0	10.7		19.0	17.8		173 184 184	5 · 5 T	ପ <b>୍</b> ଚ	16.3	18.3	18.6	0, 1	
HAMMIESS			HRC		រូក ហ	40	55	೧೮	55		56	56	55	26	nJ NJ	មា	មា	n, nj		23 13	5.6		SCS	មា បា	523	ST.	5.6	555	ŝ	
	2	NI I	8		9.2	9.0	7.3	10.6	12.5		11.9	10.4	4.4	11.5	10.5	7.5	12.0	12.4		10.4	਼- ਪੁੱ		11.3	11.5	6.5	11.9	11.9	12.4	11.8	
REDUCTION ELDING.	114	ARE 4	(2)		83.5 83.5	50.6	40.0	39.0	44.0		45.8	41.1	21,8	32,4	35.6	43.5	47.8	45.5		42.6	(1) · (1) · (1) · (1) · (1) · (1)		7.60	8.70	3.53	46.3	46.0	46.9	43.0	
	11181111	HISH SILS	(15.4)		0 10	145	126	308	310		315	317	155	260	301	141	SOE	707		30.9	-4 -4 17		1.5	3. M	1+0	600	307	<b>₹</b> 0€	20%	
	1	SIR RESIDENCE	(421)		<u> </u>	100 100 100 100 100 100 100 100 100 100	* 26	ক গ য	235	I Z	24.0 0.40	E.E.	117 *	201	212	115 *	90.7	<b>9</b> (1)	=======================================	អា ទា ()	7.5	- 7		.0.7	1111	• )	<del></del>	 <u>ਾ</u>		: · · · · · · · · · · · · · · · · · · ·
	N PHO LANCE	11 ± 3 1				Ξ		15 P.L		ទា	10 to L	7,		15 A L	Œ	:::	ic F L	î. <b>.</b>	ю <u>Т</u>	7 1	<u>~</u> 3 9.7	ננו			17.50	1717	1 / 4 / 1	1/ 20 1.		4 11 /1

<sup>· · ·</sup> with reilibre

Giana and and an all and a

APPEARS OF MO SPECIFIESS

INTERNATION OF CHARLEST STANDING

TABLE A NOTOH TENSILE TEST RESULTS

BREDIMEN COOR *		/TELD TRENGTH (" U.)	TEMSILE BTRENGTH (FG1)	REDUCTION IN AREA (%)
15 A L	**	255.1	340.9	28.3
15 A T	جو چد	238.2	320.4	22.2
15 A S	**	207.9	340.a	7.3
15 F L	4-4	271.0	U4U.2	35.5
15 P T	<del>- 14.</del>	254.9	337, 3	<b>75.</b> 2
15 W L	**	255.7	342.7	33.0
15 W T	**	271.0	351.3	I4.1
15 W S	**	279.9	350.5	11.9
16 A L	**	230.7	320.4	23.4
15 9 T	4.4	251.4	334.2	23.2
15 A S	<del>**</del> ***	238.0	335.E	11.5
15 P L	* -	<u>ರವಣ</u> ಿ ತ	J43.2	37.7
15 5 7	Sec. 144	257.8	340.1	75.9
15 W L	**	263.9	541.2	35. t
16 W T	**	257.0	347.9	J2.5
17 A L	**	250.0	<b>343.</b> 0	27.5
17 A T	***	230.0	345.9	25.2
17 A S	**	242.7	345.9	11.8
17 P L	**	259.5	341.2	36.2
17 P T	**	260.3	339.5	36.0
17 W L	**	269.9	341.1	37.3
17 W T	**	271.7	343.0	33.2

SSSS RESIDENCE SERVICES BENEFICE OF THE PROPERTY INTERCORD MANAGED BENEFICE SERVICES OF THE PROPERTY OF THE PR

<sup>\*</sup> NO TESTS FOR 15 P S,16 P S,16 W S,17 P S AND 17 W S \*\* -- AVERAGE OF TWO TESTS




FIGURE 1: Microstructure of Samples Air Cooled at 100° F per Minute




FIGURE 2: Microstructure of Samples Cooled at 500° F per Minute

200X




FIGURE 3: Microstructure of Samples Cooled at 1000° F per Minute

500X

# TENSILE PROPERITIES

excellennana visitizi eccessor bibliotici siiiiila

the Induspose President leader





FIGURE 4: The Effect of Cooling Rate During Quenching on the Tensile Properties



The Effect of Test Direction on the Strength-Ductility Relationship TENSILE STRENGTH (ksi) + S ♦ FIGURE 5:


350

330

310

0

വ



CONTRACTOR PRODUCTS STATES STATES

The Effect of Quench Rate on the Strength-Ductility Relationship for Notched Tensile Specimens Oriented in the L and T Directions FIGURE 6:

TENSILE STRENGTH (ksi)

330

310

14 +

16


8

20 —

350


STATE TO SERVICE TO SE

SATISTICS OF THE SAME AND A PROPERTY OF




CHARPY V-NOTCH ENERGY AT 80F

The Effect of Specimen Orientation on the Yield Strength, Charpy V-Notch Toughness Relationship at  $80^{\circ}~\mathrm{F}$ FIGURE 7:




The Effect of Austenitizing Temperature on the Yield Strength, Charpy V-Notch Toughness Relationship at  $-40^{\circ}\ {\rm F}$ FIGURE 8:




SSSS SASSAN ASSASSA STRANGE SSSSSS SASSAN SASSANS

Relationship Between Kq and Charpy V-Notch Energy at  $80^{\rm O}$ FIGURE 9:

CHARPY ENERGY AT 80F (ft. lbs.)




a) Sample 15AS
Orientation S
1000X




b) Sample 15AT
Orientation TL
1000X

FIGURE 10: Charpy V-Notch SFM Fractograph of Slow Cooled Samples Austenitized at  $1500^{\circ}$  F




ASSESSED FORMARY PROPERTY ON THE PARTY OF TH

a) Sample 15WTOrientation TL900X



b) Sample 15PT Orientation TL 1000X


FIGURE 11: Charpy V-Notch SEM Fractograph of Slow Cooled Sample Austenitized at  $1550^{\circ}$  F



とはなりにある。 とうとうなっかっと かっていない


COLUMN CONTRACT DESCRIPTION OF THE PROPERTY OF

a) Sample 15WS
Orientation S
1000X




b) Sample WS
Orientation S
400GX

FIGURE 12: Charpy V-Notch SEM Fractograph of Slow Cooled Sample Austenitized at  $1550^{\circ}$  F




a) Sample 16AS
Orientation S
900X




b) Sample 16AT
Orientation TL
900X

FIGURE 13: Charpy V-Notch SEM Fractograph of Slow Cooled Sample Austenitized at  $1650^{\circ}$  F



a) Sample 16WT Orientation TL 1000X




were leavourse extensive contracts encourse estations.

The second of th


b) Sample 16PT
Orientation TL
1000X

FIGURE 14: Charpy V-Notch SEM Fractograph of Samples Cooled at  $500^\circ$  F per Minute (P) and at  $1000^\circ$  F per Minute (W) Austenitized at  $1650^\circ$  F




Control of the Contro

a) Sample 17AS
Orientation S
900X




b) Sample 17AT
Orientation TL
1000X

FIGURE 15: Charpy V-Notch SEM Fractograph of Samples Austenitized at 1750° F and Quenched at 100° F per Ninute




a) Sample 17PT
Orientation TL
1000X



STATE AND STATE OF STATE OF STATE OF STATES STATES STATES

b) Sample 17WT
Orientation TL
1000X


FIGURE 16: SEM Fractograph of Charpy V-Notch Samples Austenitized at 1750° F and Quenched 500° F per Minute (Fig. 16a) and Water Quenched (Fig. 16b)



STOREST CONTRACTOR CONTRACTOR


THE DESCRIPTION OF THE PROPERTY OF THE PROPERT

a) Sample 15AL
Orientation LT
1000X




b) Sample 15PL
Orientation LT
1000X

FIGURE 17: SEM Fractograph of Slow Bend Fracture Toughness Specimen Austenitized at  $1500^{\circ}$  F




a) Sample 15WL
Orientation IT
1000X




b) Sample 16AL
Orientation LT
1000X

FIGURE 18: SEM Fractograph of Slow Bend Fracture Toughness Specimen Austenitized at  $1550^{\circ}$  F (Fig. 18a) and  $1650^{\circ}$  F (Fig. 18b)




a) Sample 16PL
Orientation LT
Austenitized 1650° F
Quenched 500° F/Min.



b) Sample 16WL
Orientation LT
Austenitized 1650° F
Quenched 500° F/Min.


FIGURE 19: SEN Fractograph of Slow Bend Fracture Toughness Specimen Austenitized at  $1650^{\circ}$  F



Mindian excesses systems


STATE STATES SECTION DESCRIPTION DESCRIPTION OF THE PARTY OF THE PARTY

a) Sample 17AL
Orientation LT
Austenitized 1750° F
Quenched 100° F/Min.



b) Sample 17PL
Orientation LT
Austenitized 1750° F
Quenched 500° F/Min.

FIGURE 20: SEM Fractograph of Slow Bend Fracture Toughness Specimen Austenitized at  $1750^{\circ}$  F



THE STATE OF STATES OF STATES STATES AND STATES STATES STATES STATES STATES STATES STATES

a) Sample 17WL


Orientation LT

Austenitized 1750° F

Quenched 1000° F/Min.




a) Sample 16W Orientation S 400X



recepted bedeem transmit british warned absorbs andstant areas


b) Sample 16W
Orientation S
2600X

FIGURE 22: Inclusions Viewed on A Plane Normal to Thru Thickness Direction



becaused beserved besteered bessessed bessessed besides

FIGURE 23: EDX-A Spectra of Inclusion "A" in Figure 22b




positional books and secretary

FIGURE 24: EDX-A Spectra from Inclusion "B" in Figure 22b



a) Sample 16W
Orientation S
2600X



b) Sample 16W
Orientation S
900X


FIGURE 25: Inclusions Viewed on A Plane Normal to The Thru Thickness Direction



STATES COLUMNO CONTRACTO CONTRACTOR CONTRACT

PROBLEM CONTROL ACCOUNTS DESCRIPTION

FIGURE 26: EDX-A Spectra from Inclusion "C" in Figure 25a



ecest assesses assesses besident consider probable

DANAMA BUDUNUN PROCESS BOXESPE SISSONS

FIGURE 27: EDX-A Spectra from Inclusion "D" in Figure 25a




FIGURE 28: EDX-A Spectra from Inclusion "E" in Figure 25b



a) Sample 16W Orientation S 2500X





FIGURE 29: Inclusion Viewed on A Plane Normal to The Thru Thickness Direction



SUSSEL BUSINESS PARACIONAL RANGESCO.

Eggetetet valabatati fantassett Ressetting Santasset Keeses

FIGURE 30: EDX-A Spectra from Inclusion "F" in Figure 29a




FIGURE 31: EDX-A Spectra from Inclusion "G" in Figure 29b



STATES CONTROL STATES STATES

THE PROPERTY OF THE PROPERTY O

Sample 16W
Orientation L
2500X

FIGURE 32: Inclusion Viewed on Plane Parallel to The Longitudinal Rolling Direction




FIGURE 33: EDX-A Spectra from Inclusion "Tail" Shown in Figure 32

a) Sample 16WOrientation T2500X

16WL6 "T" DIRECTION
20KV X2500 10U 046 LUK

b) Sample 16W Orientation T 2400X

16WL6 "T" DIRECTION 20KV X2400 10U 047 LUK

FIGURE 34: Inclusion Viewed on A Plane Parallel to The Transverse Rolling Direction




FIGURE 35: EDX-A Spectra from Inclusion "J" in Figure 34a





FIGURE 36: EDX-A Spectra from Inclusion "K" in Figure 34a



fance engages progress successful translation obstition

Managed branched the

FIGURE 37: EDX-A Spectra from Inclusion "L" in Figure 34b



a) 25X





FIGURE 38: Fracture Surface of Notch Tensile Sample 15WS. Water Quenched from  $1550^{\circ}$  F, Orientation S.



a) 28X




FIGURE 39: Fracture Surface of Notch Tensile Sample 15WT.
Water Quenched from 1550° F, Orientation S.
Figure B at Center of Specimen Fracture Surface.



a) 25X




FIGURE 40: Fracture Surface of Notch Tensile Sample 15AS.

Cooled 100 F per Minute from 1550 F, Orientation S.

Figure B A Center of Specimen Fracture Surface.



a) 26X




FIGURE 41: Fracture Surface of Notch Tensile Sample 15AT.

Cooled 100° F per Minute from 1550° F, Orientation T.

Figure B at Center of Fracture Surface.

DISTRIBUTION LIST No. of Copies To 1 Office of the Under Secretary of Defense for Research and Engineering, The Pentagon, Washington, DC 20301 Commander, Defense Technical Information Center, Cameron Station, Building 5, 5010 Duke Street, Alexandria, VA 22314 2 ATTN: DTIC-FDAC Commander, U.S. Army Laboratory Command, 2800 Powder Mill Road, Adelphi, MD 20783-1145 I ATTN: SLCIS-IM-TL Metals and Ceramics Information Center, Battelle Columbus Laboratories, 505 King Avenue, Columbus, OH 43201 1 ATTN: J. H. Brown, Jr. Commander, Army Research Office, P.O. Box 12211, Research Triangle Park, NC 27709 1 ATTN: Information Processing Office Commander, U.S. Army Materiel Command (AMC), 5001 Eisenhower Avenue, Alexandria, VA 22333 I ATTN: AMCLD Commander, U.S. Army Materiel Systems Analysis Activity, Aberdeen Proving Ground, MD 21005 l ATTN: AMXSY-MP, Director Commander, U.S. Army Armament, Munitions and Chemical Command, Dover, NJ 07801 2 ATTN: Technical Library Commander, U.S. Army Tank-Automotive Command, Warren, MI 48090 ATTN: AMSTA-ZSK 2 AMSTA-TSL, Technical Library 1 AMSTA-RCK Commander, U.S. Army Foreign Science and Technology Center, 220 7th Street, N.E., Charlottesville, VA 22901 l ATTN: Military Tech

Director, Eustis Directorate, U.S. Army Applied Technology Directorate, Fort Eustis, VA=23604

1 ATTN: SAVRT-TY-ASV, Mr. McAllister

Commander, U.S. Army Aviation Systems Command, 4300 Goodfellow Boulevard, St. Louis, MO 63120

1 ATTN: AMDAV-EGX

1 AMDAV-EX, Mr. R. Lewis 1 AMDAV-EQ, Mr. Crawford

1 AMCPM-AAH-TM, Mr. R. Hubbard

1 AMDAV-DS, Mr. W. McClane

To Commander, U.S. Air Force Wright Aeronautical Laboratories. Wright-Patterson Air Force Base, OH 45433 1 ATTN: AFWAL/MLSA, Howard W. Zoeller AFWAL/FIBC, Mr. L. G. Kelly 1 Edward J. Morrissey, AFWAL/MLTE, Wright Patterson Air Force Base, OH 45433 Air Force Flight Dynamics Laboratory, Wright-Patterson Air Force Base, OH 45433 ATTN: AFFDL/FES, J. Sparks AFFDL/TST, Library Naval Air Development Center, Warminster, PA 18974 1 ATTN: Code 063 Naval Air System Command, Department of the Navy, Washington, DC 20360 1 ATTN: AIR-5164J2 Naval Air Systems Command, Washington, DC 1 ATTN: Dr. Lewis Sloter, Head Metals Section Naval Surface Weapons Center, Dahlgren Laboratory, Dahlgren, VA 22448 ATTN: Code G-54, Mr. J. Hall Code G-54, Dr. B. Smith Bell Helicopter Textron, P.O. Box 482, Fort Worth, TX 76101 1 ATTN: W. Craig William, Senior Metallurgical Engineer, Metallurgical Laboratories Grumman Aerospace Corporation, New South Road, A04-12, Bethpage, L.I. NY 11714 1 ATTN: Technical Information Center, J. Davis McDonnell Douglas Helicopter Company, 5000 E. McDowell Road, Mesa, AZ 85205 1 ATTN: Library Mr. A. Hirko 1 1 Mr. L. Soffa IRI International, Post Office Box 1101, Pampa, TX 79065 1 ATTN: W. L. Hallerberg, V. P. Metallurgy Lockheed-Georgia Company, 86 South Cobb Drive, Marietta, GA 30063 1 ATTN: C. R. Hart, Senior Materials & Processes Engineer, Dept. 72-27, Zone 53

Box 225907, Dallas, TX 75265

1 ATTN: Stanley Klein, Senior Engineering Specialist,
Materials and Processes, M/S 220-70

LTV Aerospace and Defense Company, Vought Aero Products, P.O.

Moog Inc., East Aurora, NY 14052

1 ATTN: Robert B. Fellman, Consultant, Manager of Materials & Processes

McDonnell Aircraft Company, P.O. Box 516, St. Louis, MO 63166

1 ATTN: Byron Davis, Section Chief, Bldg. 32, Dept. 347 Material and Process Development

Parker Hannifin Corporation, Bertea Control Systems Division, 14300 Alton Parkway, Irvine, CA 92718

l ATTN: C. Beneker

Sikorsky Aircraft, A Division of United Aircraft Corporation, Main Street. Stratford, CT 06601

l ATTN: W. G. Degnan

Georgia Institute of Technology, School of Mechanical Engineering, Atlanta, GA 30332

l ATTN: Dr. J. T. Berry

Lukens Steel Company, Coatesville, PA 19320

l ATTN: E. Hamburg

A. Wilson

LTV Steel Corporation, 410 Oberlin Avenue SW, Massillon, OH 44646

1 ATTN: Mr. T. M. Costello

Boeing Commercial Airplane Company, P.O. Box 3707, M/S 73-43, Seattle, WA 98124

1 ATTN: Roger V. Carter, Manager, Metals Technology

L. Raymond and Associates, 2152 DuPont Circle, Suite 200, Irvine, CA 92715

1 ATTN: Dr. L. Raymond

Allegheny Ludlum Steel Corporation, Quality Assurance Technical Service, P.O. Box 565, Leechburg, PA 15656

1 ATTN: Joseph A. Chivinsky, Supervisor

Carpenter Technology Corporation, Technical Steel Division, P.O. Box 662, Reading, PA 19603

1 ATTN: Norman B. Schmidt, Mgr. New Prod. Dev.

Southern Research Institute, 2000 Ninth Avenue South, Birmingham, AL 35255

1 ATTN: Dr. Charles Bates, Head, Metals Section

Sun Steel Treating, 550 Mill Street, South Lyon, MI 48178

1 ATTN: Rod Denton, President

Director, U.S. Army Materials Technology Laboratory, Watertown, MA 02172-0001

ATTN: SLCMT-IML

SLCMT-IMA-P 1

SLCMT-ISC l

10 SLCMT-MB, A. Anctil

Electroslag Remelting Steel Technical Report NIL IR 86-44, October 1936 54 pp-111us.-talies, Contract DAAG46-85-C-0011 D/A Project 1Ax632150079 Final Report, January 1985 to Octuber 1986 THE EFFECT OF AUSTENITIZING CONDITIONS U.S. Army Materials Technology Laboratory Watertown, Massachusetts 02172-0001 ON THE AMISOINOPIC EMBRITILEMENT OF E. G. Hamburg and A. D. Wilson Lukens Steel Company Coatesville, PA 19320 Research Center ESH 4340 SILEL

UNLIMITED DISTRIBUTION UNCLASSIFIED

Key Words

Fracture Toughness Fractography Inclusions Anisotropy

D/A Project 1A4632150079

Fracture Toughness Fractography Inclusions Anisotropy

UNLIMITED DISTRIBUTION

Key Words

UNCLASSIFIED

Watertown, Massachusette 02172-0001 THE EFFECT OF AUSTENITIZING CONDITIONS

ON THE ANISOTROPIC EMBRITTLEMENT OF

ESR 4340 STEEL

E. G. Hamburg and A. D. Wilson Lukens Steel Company

Coatesville, PA 19320

Research Center

U.S. Army Materials Technology Laboratory

3653533

54 pp-11lus.-tables, Contract DAAG46-85-C-0011 Final Report, January 1985 to October 1986 Technical Report MTL TR 86-44, October 1986

Electrosiag Remeiting

The effect of austenftizing conditions on the anisotropic embrittlement of

direction. Reduction in area of the mild notch tensile specimen was decreased as much as 64% in the through-thickness direction when compared to the longitudinal direction. Inclusion clusters were primarily alumina with some calcium present. In all the tests conducted, there was no evidence for anisotropic embritthement of this material (i.e., intergranular fracture). electroslag remelted (ESR) 4340 areel were studied. Increasing austenfitzing temperature from 1550 F to 1750 F had little or no effect on the strength and touginess of ESR melted 4340 steel. Decreasing the quench race from 1000 F per minute to 500 F per minute had no effect on the strength and touginess. Decreasing the quench rate from 500 F per minute to 100 F per minute had a significant effect on Charpy V-norch toughness. Lower Charpy V-norch toughness ness associated with the quench rate of 100 F per minute was due to the small effect on alow bend fracture toughness. Plate anisotropy was very small in the plane of the plate (longitudinal versus transverse). Properties normal to the plane of the plate were affected drastically. Charpy V-notch toughness presence of bainite in the microstructure. The presence of bainite had a was decreased as much as 56% over the values obtained in the longitudinal

calclum present. In all the tests conducted, there was no evidence for aniso-

tropic embrittlement of this material (1.e., intergranular fracture).

tudinal direction. Inclusion clusters were primarily alumina with some

as anch as 64% in the through-thickness direction when compared to the longi-

to the plane of the plate were affected drastically. Charpy V-notch toughness direction. Reduction in area of the mild notch tensile specimen was decreased

was decreased as much as 56% over the values obtained in the longitudinal

the plate (longitudinal versus transverse). Properties normal

in the plane of

small effect on slow bend fracture toughness. Plate anisotropy was very small

alguifteant effect on Glarpy V-notch toughness. Lower Charpy V-notch toughness associated with the quench rate of 100°F per minute was due to the presence of bainite in the microstructure. The presence of bainite in the microstructure.

electrosing remeited (ESR) 4340 steel were studied. Increasing austentizing temperature from 150°F to 1750°F had little or no effect on the strength and toughness of ESR melted 4340 steel. Decreasing the quench rate from 1000°F per ainute to 500°F per minute had no effect on the strength and toughness. Decreasing the quench rate from 500°F per minute to 100°F per minute had a

The effect of austenitizing conditions on the anisotropic embrittlement of

Watertown, Massachusetta 02172-0001 THE EFFECT OF AUSTENITIZING CONDITIONS U.S. Army Materials Technology Laboratory ON THE ANISOTROPIC EMBRITLEMENT OF

E. G. Hamburg and A. D. Wilson Lukens Steel Company ESK 4340 SIEEL

Coatesville, PA 19320 Research Center

Technical Report MIL IR 86-44, October 1986 54 pp-11lus.-tables, Contract DAAG46-85-C-0011 Final Report, January 1985 to October 1986 D/A Project 1A4632150079

UNLIMITED DISTRIBUTION Fracture Toughness Key Words Fractography Inclusions Anisotropy Steel

URCLASSIFIED

Electroslag Remelting

TOUL

UNLIMITED DISTRIBUTION Electroslag Remelting Fracture Toughness UNCLASSIFIED Key Words Fractography Inclusions Anisotropy Steel LEBOT 9 Coaresville, PA 19320
Technical Report MTL TR 86-44, October 1986
54 pp-11lus-tables, Contract DAGG6-85-C-0011
D/A Project 1A663150079 Final Report, January 1985 to October 1986 Watertown, Massachusetts 02172-0001 THE EFFECT OF AUSTENITIZING CONDITIONS ON THE ANISOTROPIC ENBRITLEMENT OF U.S. Army Materials Technology Laboratory E. G. Hamburg and A. D. Wilson Lukens Steel Company Research Center ESR 4340 STEEL

to the plane of the plate were affected drastically. Charpy V-notth touphness was decreased as much as 56% over the values obtained in the longitudinal direction. Reduction in area of the mild notch tensile specimen was decreased small effect on blow bend fracture toughness. Plate inisotropy was very small in the plane of the plate (longitudinal versus transverse). Properties normal calcium present. In all the tests conducted, there was no evidence for aniso-The effect of austenitizing conditions on the anisotropic enbrittlement of electrosiag remeited (ESR) 4340 steel were studied. Increasing austenitizing temperature from 1550 F to 1750 F had little or no effect on the strength and toughness of ESR melted 4340 seeel. Decreasing the quench rate from 1000 F as much as 64% in the through-thickness direction when compared to the longisignificant effect on Gharpy V-notch toughness. Lower Charpy V-notch toughness associated with the quench rate of  $100^{\circ}\mathrm{F}$  per minute was due to the per minute to  $500^{\circ}F$  per minute had no effect on the strength and toughness. Decreasing the quench rate from  $500^{\circ}F$  per minute to  $100^{\circ}F$  per minute had a presence of bainite in the microstructure. The presence of bainite had a Inclusion clusters were primarily alumina with some tropic embrittlement of this material (1.e., intergranular fracture). tudinal direction.

spail effect on slow bend fracture toughness. Plate anisotropy was very small was decreased as much as 56% over the values obtained in the longitudinal direction. Reduction in area of the mild notch tensile specimen was decreased in the plane of the plate (longitudinal versus transverse). Properties normal to the plane of the plate were affected drastically. Charpy V-notch toughness calcium present. In all the tests conducted, there was no evidence for anisotemperature from 1550 F to 1750 F had little or no effect on the atrength and toughness of ESR melted 4340 steel were studied. Increasing austentiting temperature from 1550 F to 1750 F had little or no effect on the atrength and toughness of ESR melted 4340 steel. Decreasing the quench rate from 1000 F per minute had no effect on the strength and toughness. Decreasing the quench rate from 500 F per minute to 100 F per minute had a stguildiant effect on charpy V-notch toughness. Lower Charpy V-notch toughness ness associated with the quench rate of 100 F per minute was due to the as both as bot in the through-thickness direction when compared to the longi-The effect of austenitizing conditions on the anisotropic embrittlement of presence of bainite in the microstructure. The presence of bainite had a todinal direction. Inclusion clusters were primarily alumina with some tropic embrittlement of this material (i.e., intergranular fracture).

UNLIMITED DISTRIBUTION AD UNCLASSIFIED Technical Report NIL IR 86-44, October 1996 54 pp-111148, - Cables, Contract DAAG46-85-C-0011 U.S. Army Naterials Technology Luboratory Matercoon, Massachusetts 02172-0001 THE EFFECT OF AUSTERNITIZING CONDITIONS ON THE AMISOTROPIC EMBRITTLEMENT OF E. G. Hamburg and A. D. Wilson D/A Project 1A-632150079 Coatesville, PA 19320 Lukens Steel Company Research Center ESR 43-0 STEEL

Electroslag Remelting Tracture Toughness Key Words Fractography Inclusions Anisotropy Armor Final Report, January 1985 to October 1986

direction. Reduction in area of the mild notch tensile specimen was decreased as much as 5.2 in the through-thickness direction when compared to the longitudinal direction. Inclusion clusters were primarily alumina with some prosence of bainite in the microstructure. The presence of bainite had a banil effect on slow bend fracture toughness. Plate anisotropy was very small in the plane of the plate (longitudinal versus transverse). Properties normal to the plane of the plate were affected drastically. Charpy V-notch toughness was decreased as much as 56% over the values obtained in the longitudinal calclum present. In all the tests conducted, there was no evidence for aniso-tropic embrittlement of this material (i.e., intergranular fracture). electivalag temelted (ESR) 4340 attel were studied. Increasing austenitizing temperature from 1550 F to 1750 F had little or no effect on the etrength and temperatures of LSR melted 4340 attel. Decreasing the quench rate from 1000 F per minute had no effect on the strongth and toughness. Decreasing the quench rate from 500 F per minute had no effect on the strongth and toughness. significant effect on darpy V-notch toughness. Lower Charpy V-notch toughness associated with the quench rate of  $100^5 {\rm F}$  per minute was due to the The effect of austentitzing conditions on the anisotropic embrittlement of

UNCLASSIFIED UNLIMITED DISTRIBUTION Electroslag Remelting Fracture Toughness Key Words Fractography Inclusions Anisotropy Steel Technical Report MIL IR 86-49, October 1996 54 pp-111us.-tables, Contract DAAG46-85-C-0011 Final Report, Junuary 1985 to October 1986 Hatertoon, Hasbbenasetta 02172-0601 THE EFFECT OF ALSTERITIZING COMBILIONS U.S. Army Materials Technology Laboratory ON THE ARISOTROPIC EMBRITLEMENT OF C. Hamburg and A. D. Wilson D/A Project 1A-632150079 Coatesville, PA 19320 Lukeus Steel Company Research Center

small effect on slow bend fracture toughness. Plate antsotropy was very small in the plane of the plate (longitudinal versus transverse). Properties normal to the plane of the plate were affected drastically. Charpy V-notch toughness direction. Reduction in area of the mild notch tensile specimen was decreased tenthal direction. Inclusion clusters were primarily alumina with some calcium present. In all the tests conducted, there was no evidence for anisoelectrosing tenefled (ESR) 4340 steel were studied. Increasing sustentiting temperature from 1550 F to 1750 F had little or no effect on the strength and toughness of ESR relied 4340 steel. Decreasing the quent rate from 1000 F per minute had no effect on the strength and toughness. Per cannot to 500 F per minute had no effect on the strength and toughness. Leversing the quench rate from 500 F per minute to 100 F per minute had a significant effect on charpy V-notch toughness. Lower Charpy V-notch toughness associated with the quench rate of 1000 F per minute was due to the as than as but in the through-thickness direction when compared to the longieffect of austenitizing conditions on the anisotropic embrittlement of presence of bainite in the microstructure. The presence of bainite had a was decreased as fach as 56% over the values obtained in the longitudinal trajic empittiement of this material (i.e., intergranular fracture).

HG COMBITIONS TEMENT OF TIESON TO COOPER 1986 FACT DANG-6-85-C-0011
Final Report, January 1985 to October 1986 Electroslag Remelting

TO COLUMN TO COL

in the plane of the plate (longitudinal versus transverse). Properties normal to the plane of the plate were affected drastically. Charpy V-notch toughness tudinal direction. Inclusion clusters were primarily alumina with some calcium present. In all the tests conducted, there was no evidence for anisosmall effect on alow bend fracture toughness. Plate anisotropy was very small direction. Reduction in area of the mild notch tensile specimen was decreased The effect of austenitizing conditions on the anisotropic erbrittlement of electrosing remeled (ESR) 4340 steel were studied. Increasing austenitizing temperature from 1500 F to 1750 F had little or no effect on the strength and toughness of ESR melted 4340 steel. Decreasing the quench rate from 1000 per minute to 500 F per minute had no effect on the strength and toughness. Decreasing the quench rate from 500 F per minute to 100 F per minute had a significant effect on tharpy "-north toughness. Lower Charpy V-north toughness. Lower Charpy V-north toughness ness associated with the quench rate of 100 F per minute was due to the presence of bainite in the microstructure. The presence of bainite had a as much as 64% in the through-thickness direction when compared to the longiwas decreased as much as 56% over the values obtained in the longitudinal tropic embrittlement of this material (i.e., intergranular fracture).

U.S. Army Materials Technology Laboratory	ΥD
Watertown, Massachusetts 02172-6001	UNCLASSIFIED
THE EFFECT OF AUSTENITIZING CONDITIONS	UNLIMITED DISTRIBUTION
ON THE AMISOTROPIC EMBRITTLEMENT OF	
ESR 4340 STEEL	Key Words
E. G. Hamburg and A. D. Wilson	
Lukens Steel Company	Steel
Research Center	Fractography
Coaresville, PA 19320	Anisotropy
Technical Report MTL TR 86-44, October 1986	Fracture Toughness
54 pp-111ustables, Contract DAAG46-85-C-0011	Inclusions
D/A Project 1A4632150079	Armor
Final Report, January 1985 to October 1986	Electroslag Remelting

small effect on slow bend fracture toughness. Plate anisotropy was very small to the plane of the plate were affected drastically. Charpy V-notch toughness was decreased as much as 56% over the values obtained in the longitudinal direction. Reduction in area of the mild notch tensile specimen was decreased tudinal direction. Inclusion clusters were primarily alumina with some calcium present. In all the tests conducted, there was no evidence for anisotropic embrittlement of this material (i.e., intergranular fracture). The effect of austenitizing conditions on the anisotropic embrittlement of electrosing remelted (ESR) 4340 steel were studied. Increasing austenitizing temperature from 1550°F to 1750°F bad little or no effect on the strength, and poughness of ESR melted 4340 steel. Decreasing the quench rate from 1000°F per minute to 500°F per minute had no effect on the strength and toughness. Decreasing the quench rate from 500°F per minute had a significant effect on Charpy V-notch toughness. Lower Charpy V-notch toughness associated with the quench rate of 100°F per minute was due to the presence of bainite in the natrostructure. The presence of bainite had a in the plane of the plate (longitudinal versus transverse). Properties normal as nuch as tal in the through-thickness direction when compared to the longi-